Regulations Report - November 8th, 2018 to January 9th, 2019

Permit No.			Date In	Date Out	Turn-around	Proposed Works	Permit Category	Waterbody	Municipality
COMPLETED PERMITS									
0	91	18	18-Oct-18	23-Nov-18	36	replace decks	Buildings	Belmont Lake	HBM
1	29	18	22-Nov-18	4-Dec-18	12	shoreline restoration	Shoreline	Belmont Lake	HBM
1	76	18	11-Dec-18	12-Dec-18	1	amended permit	Shoreline	Crowe River	Marmora & Lake
1	83	18	9-Nov-18	20-Nov-18	11	driveway	Fill	Crowe River	Trent Hills
1	95	18	17-Oct-18	27-Nov-18	41	replace septic system	Fill	Wetlands	Marmora & Lake
1	96	18	16-Oct-18	30-Nov-18	45	foundation repair, addition, screen room, deck	Buildings	Crowe River	Trent Hills
1	97	18	22-Oct-18	27-Nov-18	36	shoreline restoration	Shoreline, Fill	Round Lake	HBM
1	98	18	22-Oct-18	19-Nov-18	28	foundation repair and new deck and porch	Buildings	Chandos Lake	North Kawartha
1	99	18	23-Oct-18	13-Dec-18	51	addtion	Buildings	Belmont Lake	HBM
2	0	18	7-Nov-18	23-Nov-18	16	shoreline restoration	Shoreline, Fill	Cordova Lake	HBM
2	2	18	7-Nov-18	20-Nov-18	13	additon	Building	Chandos Lake	North Kawartha
2	3	18	26-Nov-18	3-Dec-18	7	shoreline restoration	Shoreline	Round Lake	HBM
2	5	18	2-Nov-18	23-Nov-18	21	dock	Docks	Glanmire Lake	Tudor & Cashel
2	6	18	9-Nov-18	23-Nov-18	14	septic system installation	Fill	Wollaston Lake	Wollaston
2	7	18	14-Nov-18	4-Dec-18	20	storage building	Building	Steenburg Lake	Limerick
2	10	18	13-Nov-18	5-Dec-18	22	replace decks	Building	Kasshabog Lake	HBM
2	12	18	16-Nov-18	4-Dec-18	18	Addition and new garage	Building	Paudash Lake	Highlands East
2	14	18	16-Nov-18	4-Dec-18	18	boathouse	Building	Chandos Lake	North Kawartha
2	17	18	21-Nov-18	11-Dec-18	20	shoreline restoration	Shoreline	Cordova Lake	HBM
2	19	18	23-Nov-18	5-Dec-18	12	deck	Building	Crowe Lake	Marmora & Lake
2	21	18	27-Nov-18	5-Dec-18	8	replace septic system	Fill	Crowe River	Marmora & Lake
2	22	18	3-Dec-18	8-Jan-19	36	new dwelling and attached garage	Building	Belmont Lake	HBM
2	23	18	3-Dec-18	11-Dec-18	8	addition	Building	Cordova Lake	HBM
2	25	18	6-Dec-18	2-Jan-19	27	shoreline restoration	Fill	Crowe River	Marmora & Lake
2	26	18	6-Dec-18	2-Jan-19	27	shoreline restoration	Fill	Crowe River	Marmora & Lake
2	27	18	6-Dec-18	2-Jan-19	27	shoreline restoration	Fill	Crowe River	Marmora & Lake

Permit Statistics	
Permits Issued	26
Calendar Days	62
Working Days	41
Mean Turn-Around Time	
Calendar Days	22.12
Permits per Day	
Permits / Calendar Day	0.42
Permits / Working Days	0.63

Property Inquiries
`

Non Compliance	
Violations	
Resolved	2
Received	3
Total Open	22