


November 19, 2020 CVCA Board Meeting Regulations Permit Reporting Reporting Period: September 11, 2020 to November 9, 2020				Reporting Period Summary				
				Permits Issued	40	Mean Turnaround	45.55	
				Calendar Days	59	Permit / Cal. Day	0.68	
				Working Days	41	Permit / Work day	0.98	
				Property inquiries received:		40	Property inquiries complete: 39	
Permit no.	Application Complete	Permit Issued	Township	Regulated Feature	Turnaround (Cal. Days)	Application Type	Project Details	
013/20	Sep/3/2020	Sep/18/2020	Stirling-Rawdon	Rylstone Lake, PSW	15	Water crossing (culvert or bridge)	construct replacement bridge and improve existing path system	
038/20	Aug/20/2020	Sep/11/2020	HBM	North River	22	Buildings	build accessory structure near watercourse	
040/20	Aug/3/2020	Oct/8/2020	North Kawartha	Chandos Lake	66	Buildings	rebuild existing boathouse	
056/20	Oct/16/2020	Oct/30/2020	Highlands East	Paudash Lake	14	Buildings	new dwelling with walkout basement and install septic system	
071/20	Aug/21/2020	Oct/14/2020	HBM	Oak Lake	54	Shoreline erosion protection	reconstruction of vertical wall (amourestone) and install steps for wate access point	
082/20	Aug/21/2020	Oct/7/2020	Marmora and Lake	Crowe Lake	47	Fill / grading	install limestone steps for water access point	
084/20	Sep/24/2020	Oct/15/2020	North Kawartha	Chandos Lake	21	Buildings	repairs to in-water boathouse	
085/20	Oct/2/2020	Oct/6/2020	HBM	Belmont Lake	4	Buildings	construct new detached garage	
091/20	Jun/26/2020	Oct/19/2020	Highlands East	Paudash Lake	115	Buildings, fill / grading	Deck reconstruction near shoreline; construct small kayak launch area.	
093/20	Jun/30/2020	Sep 29 2020	North Kawartha	Chandos Lake	91	Shoreline erosion protection	100ft + of shoreline erosion protection using natural stone boulders, 1 row of armourstone at top	
098/20	Jul/9/2020	Oct/9/2020	Tudor and Cashel	Glanmire Creek	92	Water crossing (culvert or bridge)	rebuild existing causeway with existing culvert after washout due to high seasonal flows	
100/20	Jul/15/2020	Oct/15/2020	Highlands East	Paudash Lake	92	Fill / grading	Replace septic system	
103/20	Jul/9/2020	Sep/11/2020	HBM	Wetland - Cordova Lake	64	Fill / grading	add fill to raise level of an existing driveway to provide safe access to an existing cottage	
106/20	Jul/15/2020	Sep/29/2020	HBM	Belmont Lake	76	Buildings	demolish existing dwelling and construct a new 64'x60' dwelling with a partial full basement partial crawlspace, 48' from the shoreline	
112/20	Jul/17/2020	Sep/11/2020	Stirling-Rawdon	Rylstone Lake	56	Buildings, fill / grading	building a new dwelling 60' from the roadside property line and install a 1000 gellan septic tank and bed	
113/20	Aug/21/2020	Oct/15/2020	Marmora and Lake	Crowe Lake	55	Shoreline/watercourse	80' of shoreline protection by installing 1 row high of armourstone on a gabion stone base with 3/4" clear stone backfill	
114/20	Aug/21/2020	Oct/15/2020	HBM	Belmont Lake	55	Shoreline/watercourse	48' of shoreline protection by removing concrete shore and install natural field stone at a 3:1 slope and 1	
117/20	Jul/16/2020	Sep/11/2020	North Kawartha	Clydesdale Lake	57	Buildings, fill / grading	Construct deck and staircase onto existing dwelling; construct 2 accessory buildings (sheds); Fill removal/replacement	
118/20	Aug/21/2020	Oct/15/2020	HBM	Cordova Lake	55	Shoreline erosion protection	Work on 70 ft of shoreline: Along 55' Remove existing failed railway tie retaining wall, replace with armour stone with gabion stone base; along 15' install rip-rap	
121/20	Aug/5/2020	Oct/29/2020	Marmora and Lake	Crowe Lake	85	Buildings, shoreline erosion protection	replace existing damaged boathouse (same size and location) and install 3:1 sloped rip-rap	
124/20	Jul/27/2020	Oct/30/2020	Wollaston	Wetlands	95	Buildings	building a 12'x22' car port being 84' from the road and 120' from low lying area	
132/20	Aug/7/2020	Nov/3/2020	HBM	Round Lake	88	Fill / grading	Replace failed septic system	
137/20	Aug/13/2020	Sep/16/2020	North Kawartha	Chandos Lake	34	Fill / grading	construct 127' driveway	
141/20	Sep/10/2020	Sep/17/2020	North Kawartha	Chandos Lake	7	Shoreline erosion protection	replace deteriorating wood retaining wall at top of slope, 65' upland from the shoreline	
142/20	Aug/14/2020	Oct/30/2020	Highlands East	Paudash Lake	77	Fill / grading	install new filter bed septic system 52' from the shoreline	
143/20	Aug/12/2020	Nov/3/2020	Marmora and Lake	Wetland	83	Buildings	building a 24'x24' garage with cement pad on grade, 54' from a wetland	
146/20	Aug/18/2020	Oct/29/2020	HBM	Kasshabog Lake	72	Buildings, fill / grading	Construct 3,215 sq ft dwelling, slab on grade, 73' from the shoreline; construct 40'x25' garage, 227' from the shoreline; and install septic system	
150/20	Aug/31/2020	Sep/15/2020	Highlands East	Paudash Lake	15	Buildings	construct 720 sq ft addition plus deck onto an existing cottage, 100' from the shoreline - spetic system outside the regulated zone	
154/20	Aug/26/2020	Sep/23/2020	Marmora and Lake	Beaver Creek	28	Buildings	construct 2-storey garage near Beaver Creek and wetlands	

November 19, 2020 CVCA Board Meeting Regulations Permit Reporting Reporting Period: September 11, 2020 to November 9, 2020				Reporting Period Summary				
				Permits Issued	40	Mean Turnaround	45.55	
				Calendar Days	59	Permit / Cal. Day	0.68	
				Working Days	41	Permit / Work day	0.98	
				Property inquiries received:		40	Property inquiries complete: 39	
Permit no.	Application Complete	Permit Issued	Township	Regulated Feature	Turnaround (Cal. Days)	Application Type	Project Details	
160/20	Sep/1/2020	Oct/16/2020	Marmora and Lake	Lake of Islands	45	Buildings, fill / grading	construct cottage and install septic system	
166/20	Sep/14/2020	Oct/16/2020	Trent Hills	Wetland	32	Fill / grading	replace failed septic system	
167/20	Sep/9/2020	Oct/5/2020	Tudor and Cashel	Wadsworth Lake	26	Water crossing (culvert or bridge)	Rehabilitation of Weslemkoon Lake Rd from the north end of Wadsworth Lake to Gunter Lake Rd. Involves: replacement of culverts, drains, ditching, road construction and paving.	
169/20	Sep/9/2020	Sep/18/2020	Marmora and Lake	Dickey Lake	9	Water crossing (culvert or bridge)	replace a failed culvert with a new 1050mm x 17m CSP culvert	
170/20	Sep/5/2020	Oct/9/2020	Highlands East	Paudash Lake	34	Fill / grading	Install new septic system 26m from the shoreline	
181/20	Sep/16/2020	Oct/5/2020	North Kawartha	Chandos Lake	19	Buildings	Raise dwelling and excavate crawlspace, construction of addition to attic, all on existing footprint. 70' from the shoreline.	
191/20	Sep/28/2020	Sep/30/2020	Tudor and Cashel	Glanmire Lake	2	Fill / grading	Repalce failed septic system, 80' from shoreline	
192/20	Sep/28/2020	Oct/9/2020	North Kawartha	Chandos Lake	11	Fill / grading	Repalce and expand septic system, 85' from shoreline	
194/20	Sep/24/2020	Sep/30/2020	Tudor and Cashel	Mephisto Lake	6	Fill / grading	Repalce failing septic system, leaching bed moved from 21m to 30m away from shoreline	
205/20	Oct/14/2020	Oct/16/2020	Marmora and Lake	Beaver Creek	2	Fill / grading	Install septic system 115' from the shoreline of Beaver Creek	
211/20	Nov/2/2020	Nov/3/2020	HBM	Belmont Lake	1	Fill / grading	Replace septic system, 66' from shoreline	