




September 19, 2019 CVCA Board Meeting Regulations Permit Reporting Reporting Period: June 12, 2019 to September 10, 2019	Reporting Period Summary				
	Permits Issued	81	Mean Turnaround	19.85	
	Calendar Days	90	Permit / Cal. Day	0.90	
	Working Days	64	Permit / Work day	1.27	
	Property Inquiries	32			


Permit no.	Application Submitted	Application Complete	Permit Issued	Township	Waterbody / Regulated Feature	Turnaround (Cal. Days)	Permit Complexity	Application Type	Project Details
025/19	Mar/12/2019	May/17/2019	Jun/24/2019	Wollaston	Wollaston Lake	38	Minor	Shoreline	160' of shoreline protection with 2:1 granite gabion stone wall with one 18" armourstone wall behind high water mark as a barrier
026/19	Mar/12/2019	May/17/2019	Jun/24/2019	Wollaston	Wollaston Lake	38	Minor	Shoreline	120' of shoreline protection with 2:1 granite gabion stone wall with one 18" armourstone wall behind high water mark as a barrier
041/19	Apr/11/2019	Jul/22/2019	Jul/22/2019	North Kawartha	Chandos Lake	0	Minor	Shoreline	18'x18' firepit patio with a granite boulder fire pit attached to a 100' of stone staircase 4'w from the existing dwelling to the dock and 250' os shoreline restoration
045/19	Apr/23/2019	Jun/18/2019	Jun/19/2019	Faraday	Bow Lake	1	Minor	Buildings	removing existing cabin and constructing a new 54'x78' single storey dwelling with a full basement and an attached garage being 52' from the shoreline and the installation of a septic system being 120' from the shoreline (outside the regulated zone)
052/19	Apr/30/2019	Jun/14/2019	Jun/14/2019	HBM	Belmont Lake	0	Minor	Buildings	existing structure burned down so using the existing foundation to rebuild a 2 storey dwelling with a walk out basement with a new deck and addition and garage not any closer to the land than the existing which is 37'2"/11.324m & using the existing septic system
054/19	May/3/2019	May/7/2019	Jun/19/2019	HBM	Kasshabog Lake	43	Minor	Buildings	building a 24'x24' - 1-1/2 storey addition to the west side of the existing dwelling being 31.9' from the shoreline on wood piers and demolishing existing in water boathouse. New septic will be on a separate application
055/19	May/3/2019	Jul/24/2019	Jul/30/2019	HBM	Oak Lake	6	Major	Buildings	to install a 27'2" x 9'7" sunroom on an existing deck being 86' from the shoreline
057/19	May/10/2019	Jun/6/2019	Jun/14/2019	North Kawartha	Wetlands	8	Minor	Buildings	building a new 24'x30' addition (attached garage with living space above) being 134' from the shoreline
058/19	May/15/2019	Jun/17/2019	Jun/25/2019	Marmora and Lake	Beaver Creek	8	Minor	Shoreline	22m of shoreline restoration by removing the existing wood retaining wall and building a new 3 tier armourstone wall
061/19	May/21/2019	May/27/2019	Jun/18/2019	Highlands East	Paudash Lake	22	Minor	Buildings	building a new replacement shed 12'x17' on cement piers being 7' from the shoreline. Will be in the exact same footprint as the old shed
062/18	May/22/2019	May/22/2019	Jul/10/2019	Trent Hills	Crowe River and wetlands	49	Minor	Buildings; Fill/Grading	building a new 43'x45' dwelling including decks with a cralspace basement singelstory being 32' from Crowe River Rd, building a 24'x32' garage being 53' from the road and installing a new septic system bieng 64' from the road
064/19	May/13/2019	May/13/2019	Jun/14/2019	Wollaston	Deer River	32	Minor	Buildings	to build a 32'x40' steel storage building 350' from the shoreline of Deer River
066/19	May/24/2019	May/24/2019	Jul/9/2019	Wollaston	Wetlands	46	Minor	Fill/Grading; Watercourse Crossing	to enlarge an existing parking lot, remove and clear cedar trees, brush and debris and install a culvert across railway bed
067/19	May/24/2019	May/31/2019	Jun/21/2019	HBM	Plato Creek and PSW	21	Minor	Buildings	building a 32.7'x48.4' addition to the Ethonal Facility existing building 50m from wetlands and 400m from Plato Creek
068/19	May/27/2019	May/31/2019	Jun/28/2019	Tudor and Cashel	Gunter Lake	28	Minor	Buildings	building a proposed new deck ("A") to an existing deck being 60' from the shoreline then building a set of 10 stairs from deck "A" to proposed deck platform 4'x4' "B" then building a set of 10 step stairs down to another proposed deck platfor 6'x6' "C" then building a set of 18 stairs down t the shoreline for water access. Finally extending the existing platform connected to the existing dock by 12'x12'
069/19	May/27/2019	May/31/2019	Jun/17/2019	HBM	Oak Lake	17	Minor	Buildings	replacing an existing 20'x5' dock with a cable lift type of dock of same size
070/19	May/29/2019	May/29/2019	Jun/19/2019	HBM	Kasshabog Lake	21	Minor	Buildings; Fill/Grading	build a new 62'x46' 2 storey dwelling with a crawlspace foundation being 76' from the shoreline and install new septic system 5' behind new structure and add fill for driveway

September 19, 2019 CVCA Board Meeting Regulations Permit Reporting Reporting Period: June 12, 2019 to September 10, 2019	Reporting Period Summary				
	Permits Issued	81	Mean Turnaround	19.85	
	Calendar Days	90	Permit / Cal. Day	0.90	
	Working Days	64	Permit / Work day	1.27	
	Property Inquiries	32			

Permit no.	Application Submitted	Application Complete	Permit Issued	Township	Waterbody / Regulated Feature	Turnaround (Cal. Days)	Permit Complexity	Application Type	Project Details
071/19	May/29/2019	May/29/2019	Jun/28/2019	HBM	Belmont Lake	30	Minor	Buildings	building a 40'x25' single storey addition with a crawl space foundation being 49'5" from the shoreline & the new septic is outside the CVCA regulated zone
072/19	May/29/2019	May/29/2019	Jun/17/2019	HBM	Round Lake	19	Minor	Buildings	repair existing 16'x18' covered entry by rebuilding foundation, deck and supports for existing roof (existing roof to be retained) being 75' from the shoreline
074/19	May/29/2019	May/29/2019	Jun/25/2019	North Kawartha	Chandos Lake	27	Minor	Shoreline	60m of shoreline protection using 8"-20" clean rock at a 2:1 slope with non woven geotextile in behind
075/19	May/29/2019	May/29/2019	Jul/12/2019	North Kawartha	Chandos Lake	44	Minor	Shoreline	28m/90' of shoreline protection with 4" to 20" granite rip rap boulders on a woven geo textile cloth at a min 2:1 slope
077/19	May/30/2019	Jun/7/2019	Jul/12/2019	HBM	Crowe River	35	Minor	Buildings	raise the existing dwelling 2' using steel beams, precast blocks and posts due to being on a flood plain being 19' from the shoreline
078/19	May/31/2019	May/31/2019	Jul/5/2019	North Kawartha	Chandos Lake	35	Minor	Fill/Grading; Buildings	grading a 12'x14' area by raising the grade with compacted 5/8 granular, install 8'x8' patio slabs and a 4'w flagstone skirt around the patio slabs in order to build a 10'x10' gazebo with a hot tub being 14m from the shoreline
079/19	Jun/3/2019	Jun/3/2019	Jun/17/2019	North Kawartha	watercourse, wetlands	14	Minor	Fill/Grading	replace 40 year old septic system in the exact same location being 48m to the Cty Rd 504
080/19	Jun/3/2019	Jul/15/2019	Jul/31/2019	North Kawartha	Chandos Lake	16	Minor	Buildings; Shoreline	building a new 28'x32' dwelling with a full cement block foundation 4' below grade or until they hit bedrock with a 8'x12' screened in porch & 2 covered decks with a footprint of 6'x32' & 8'x34' being setback 27' from the shoreline and 30m of shoreline work at a 2:1 slope with granite boulders with 1 row of armourstone just behind to keep vegetation behind and 1 row of armourstone retaining wall 40' back from the shoreline
082/19	May/31/2019	May/31/2019	Jul/10/2019	HBM	Round Lake	40	Minor	Fill/Grading	to bury electrical wire and water hose and then refill trenches to original conditions
084/19	Jun/4/2019	Jun/4/2019	Aug/7/2019	North Kawartha	Chandos Lake	64	Minor	Buildings; Fill/Grading	demolish existing dwelling and building a new 2500sqft on perimeter foundation to bedrock being a crawl space includes replacement of attached deck on existing deck footprint. Install new septic system on an enlarged footprint and finally a new landscaped patio 700sqft to be placed on existing patio footprint being 20'9" to the shoreline
085/19	Jun/5/2019	Jun/5/2019	Jun/17/2019	Marmora and Lake	Dickey Lake	12	Minor	Buildings	building a 16'x18' storage shed on cement blocks on a cement floating pad foundation being 100' from the shoreline
087/19	Jun/7/2019	Jun/24/2019	Jul/31/2019	Marmora and Lake	Dickey Lake	37	Minor	Buildings	repair existing lower 8'x8' deck by replacing floor boards and railings and then adding an extra 8'x8' to the lower deck to make it 16'x16'. Replacing existing stairs from lower deck down to the dock platform. Replace jet float dock with a floating dock and ramp and the ramp will be secured to the existing dock platform
089/19	Jun/13/2019	Jun/13/2019	Jul/5/2019	Marmora and Lake	Thanet Lake, watercourse, MNRF and County of Hastings wetlands	22	Minor	Buildings	building a 27'Lx10'D deck being 100' from the shoreline
090/19	Jun/13/2019	Jun/25/2019	Jul/18/2019	North Kawartha	Chandos Lake, Watercourse, MNRF & Cty of Peterboro wetlands	23	Major	Buildings	building a 40'wx36'd dwelling with a full basement & ICF foundation and installation of a new septic system all being setback 100' from the road
091/19	Jun/14/2019	Jun/14/2019	Jul/26/2019	Tudor and Cashel	Steenburg Lake	42	Minor	Buildings	building a 32'x32'x7' "L" shaped deck on lake side of existing dwelling on 12" concrete filled sono tubes to a 24" "Big Foot" footing 48" below grade or to bedrock being 64' from the shoreline
092/19	Jun/14/2019	Jun/14/2019	Jul/5/2019	Marmora and Lake	Beaver Creek	21	Minor	Buildings	building a 24'x16' shed in the back of the property being approximatley 58m from the shoreline

September 19, 2019 CVCA Board Meeting Regulations Permit Reporting Reporting Period: June 12, 2019 to September 10, 2019	Reporting Period Summary				
	Permits Issued	81	Mean Turnaround	19.85	
	Calendar Days	90	Permit / Cal. Day	0.90	
	Working Days	64	Permit / Work day	1.27	
	Property Inquiries	32			

Permit no.	Application Submitted	Application Complete	Permit Issued	Township	Waterbody / Regulated Feature	Turnaround (Cal. Days)	Permit Complexity	Application Type	Project Details
093/19	Jun/14/2019	Jul/5/2019	Jul/5/2019	Marmora and Lake	Beaver Creek	0	Minor	Buildings	fixing up existing 12'x40' deck in the exact same footprint on sono tubes filled with concrete on big foot footings 4' below grade 130' from the shoreline
094/19	Jun/17/2019	Jun/18/2019	Jul/9/2019	Highlands East	Paudash Lake	21	Minor	Buildings	straighten foundation piers and replace as necessary; rebuild the existing deck
095/19	Jun/17/2019	Jun/18/2019	Jul/9/2019	HBM	PSW & watercourse	21	Minor	Watercourse Crossing	replacing an existing 47'x5' steel culvert with two 47'x36" plastic culverts
096/19	Jun/18/2019	Jun/19/2019	Jul/10/2019	Highlands East	Big Harding Lake	21	Minor	Buildings	building a 2000sqft dwelling with an ICF crawlspace foundation being 23.8m from the shoreline and installation of a new septic which is outside the CVCA regulated area
097/19	Jun/19/2019	Jun/19/2019	Jul/9/2019	HBM	Drainage Ditch	20	Minor	Watercourse Crossing	cross culvert replacement
098/19	Jun/19/2019	Jun/19/2019	Jul/9/2019	HBM	Drainage Ditch	20	Minor	Watercourse Crossing	cross culvert replacement
100/19	Jun/19/2019	Jun/19/2019	Jul/4/2019	HBM	drainage Ditch, wetlands, watercourse	15	Minor	Watercourse Crossing	cross culvert replacement
101/19	Jun/19/2019	Jun/19/2019	Jul/4/2019	HBM	drainage Ditch, wetlands, watercourse	15	Minor	Watercourse Crossing	cross culvert replacement
102/19	Jun/19/2019	Jun/19/2019	Jul/4/2019	HBM	drainage ditch wetlands	15	Minor	Watercourse Crossing	cross culvert replacement
103/19	Jun/19/2019	Jun/19/2019	Jul/4/2019	HBM	drainage ditch, wetlands	15	Minor	Watercourse Crossing	cross culvert replacement
104/19	Jun/19/2019	Jun/19/2019	Jul/4/2019	HBM	drainage ditch, wetlands	15	Minor	Watercourse Crossing	cross culvert replacement
105/19	Jun/24/2019	Jun/24/2019	Jul/11/2019	Limerick	Wadworth Lake, watercourse, wetlands	17	Minor	Watercourse Crossing	culvert replacements
106/19	Jun/28/2019	Jul/2/2019	Jul/24/2019	HBM	Crowe River	22	Minor	Buildings	building a 15'x18' (270sqft) addition laterally on the east side of the existing 18'x30' (540sqft) dwelling with no basement on pier footings being 10' from the shoreline
111/19	Jul/4/2019	Jul/16/2019	Aug/7/2019	HBM	North River/Round Lake	22	Minor	Buildings; Fill/Grading	heritage home being moved onto a new basement and a new septic system
112/19	Jul/5/2019	Jul/5/2019	Jul/23/2019	North Kawartha	Chandos Lake	18	Minor	Fill/Grading	installing a new filter bed being 76' from the shoreline
114/19	Jul/9/2019	Jul/15/2019	Jul/31/2019	Marmora and Lake	Crowe Lake	16	Minor	Shoreline	60' of shoreline protection with natural stone boulders at a 2:1 slope
115/19	Jul/9/2019	Jul/9/2019	Aug/8/2019	Marmora and Lake	Dickey Lake	30	Minor	Buildings	building a 1800sqft 2 storey dwelling with a full basement 3' above grade being 85' from the shoreline and install new septic (septic outside of regulated area)
116/19	Jul/10/2019	Jul/10/2019	Jul/29/2019	Marmora and Lake	Beaver Creek	19	Minor	Buildings	building a new 30'x60' (1800sqft) dwelling on a slab foundation on grade being 100' from Beaver Creek
117/19	Jul/12/2019	Jul/16/2019	Aug/1/2019	HBM	Crowe River	16	Major	Buildings; Fill/Grading	reconstruction of a garage lost in a fire, elevation of driveway and septic system upgrade
118/19	Jul/15/2019	Jul/18/2019	Aug/12/2019	HBM	watercourses	25	Minor	Fill/Grading	two loads of gravel being placed at south east side of the property for 10-12 portable storage units to be placed on top of it.
119/19	Jul/15/2019	Jul/15/2019	Aug/8/2019	Marmora and Lake	Crowe Lake	24	Minor	Shoreline	repairing 36' of shoreline wall by moving and replacing stones to the correct location
121/19	Jul/15/2019	Jul/18/2019	Aug/9/2019	Highlands East	PSW	22	Minor	Buildings	building a 24'x24' garage being 120m from the road
122/19	Jul/16/2019	Jul/22/2019	Jul/30/2019	HBM	Wetlands	8	Minor	Buildings	building a new 30'x30' garage 30' from the existing dwelling
123/19	Jul/16/2019	Jul/19/2019	Jul/31/2019	Marmora and Lake	Crowe River	12	Minor	Shoreline; Fill/Grading	to install armourstone anchor points at the shoreline for a lift up dock - 12'x22' concrete pad for a gazebo - 4'x32' stone retaining wall around an existing garden and 4'wc12" "U" shaped walkway from flat area to grade by concrete pad
124/19	Jul/16/2019	Jul/22/2019	Jul/26/2019	Highlands East	Paudash Lake	4	Minor	Buildings	building a new 34'x22' garage being 242' from the shoreline
126/19	Jul/19/2019	Jul/31/2019	Aug/2/2019	Highlands East	Deer Creek	2	Minor	Buildings; Fill/Grading	closing in the existing 5'x8' covered entry 5.49m from the shoreline and the replacement of the existing septic system
127/19	Jul/22/2019	Jul/22/2019	Aug/2/2019	Tudor and Cashel	Glanmire Lake	11	Minor	Fill/Grading	building up grade to keep flood waters away from the cottage being 10'wc150'lx2'd
129/18	Jul/22/2019	Jul/24/2019	Jul/31/2019	Tudor and Cashel	Glanmire Lake	7	Minor	Buildings; Fill/Grading	building a 24'x36' (864sqft) bungalow dwelling, installing a 12'w gravel driveway and installing a septic system being 113' from the shoreline

September 19, 2019 CVCA Board Meeting Regulations Permit Reporting Reporting Period: June 12, 2019 to September 10, 2019	Reporting Period Summary				
	Permits Issued	81	Mean Turnaround	19.85	
	Calendar Days	90	Permit / Cal. Day	0.90	
	Working Days	64	Permit / Work day	1.27	
	Property Inquiries	32			

Permit no.	Application Submitted	Application Complete	Permit Issued	Township	Waterbody / Regulated Feature	Turnaround (Cal. Days)	Permit Complexity	Application Type	Project Details
130/19	Jul/23/2019	Jul/25/2019	Aug/15/2019	Highlands East	Paudash Lake	21	Minor	Buildings	construction of a new residence
131/19	Jul/23/2019	Aug/19/2019	Sep/5/2019	North Kawartha	Chandos Lake	17	Minor	Buildings	construction of a 8'x4' breezeway connected from the existing porch to the new 26'x26' garage being 62' from the shoreline
132/19	Jul/23/2019	Jul/23/2019	Aug/15/2019	North Kawartha	wetlands and watercourses	23	Minor	Fill/Grading	rehabilitation of both roads including culvert replacement ditching graveling 50mm of hot asphalt
133/19	Jul/26/2019	Jul/26/2019	Aug/13/2019	HBM	Oak Lake	18	Major	Buildings	building a 137sqft addition to the east side of the existing cottage 47' from the shoreline, building a 4'6"x10' deck 77' from the shoreline and 6'x8' balcony 41' from the shoreline
134/19	Jul/26/2019	Jul/30/2019	Aug/14/2019	HBM	Oak Lake	15	Major	Buildings; Fill/Grading	rebuilding a new 2733sqft cottage with poured cement foundation crawlspace 20' from the shoreline, building 28'x26' storage building on a floating cement pad on grade 91' from the shoreline and install a new septic 78' from the shoreline
136/19	Jul/29/2019	Jul/31/2019	Aug/9/2019	Stirling-Rawdon	wetlands	9	Minor	Buildings; Fill/Grading	building a 70'x54' dwelling with a full basement and a 46'x38' attached garage by way of a breezeway between the house and garage and the installation of a new septic system
137/19	Jul/29/2019	Aug/6/2019	Aug/28/2019	Highlands East	Paudash Lake	22	Minor	Buildings	building a 28'x20' "L" shaped deck being 47.5' from the shoreline
140/19	Aug/2/2019	Aug/2/2019	Aug/28/2019	HBM	Round Lake	26	Minor	Buildings	new 4'x10' cantilevered dock and 4'W 7 stairs down to the new dock
141/19	Aug/6/2019	Aug/12/2019	Aug/16/2019	HBM	Kasshabog Lake	4	Minor	Shoreline	220' of shoreline restoration by installing natural stone boulders at a 2:1 slope
144/19	Aug/9/2019	Aug/9/2019	Aug/19/2019	Highlands East	Paudash Lake	10	Minor	Fill/Grading	landscaping
145/19	Aug/9/2019	Aug/8/2019	Sep/6/2019	HBM	Belmont Lake	29	Minor	Buildings	repairing the deck footings that were damaged by a tree fall on it being 10' from the shoreline
147/19	Aug/14/2019	Aug/14/2019	Sep/4/2019	North Kawartha	Chandos Lake	21	Minor	Shoreline	shoreline erosion control works - 60 ft of rip rap at a 3:1, some placed under failed concrete
148/19	Aug/14/2019	Aug/14/2019	Sep/4/2019	North Kawartha	Chandos Lake	21	Minor	Shoreline	shoreline erosion control works - 100 ft of rip rap at 3:1, stairs 4ft wide
149/19	Aug/14/2019	Aug/14/2019	Sep/4/2019	North Kawartha	Chandos Lake	21	Minor	Shoreline	shoreline erosion control works - 100 ft of rip rap at 3:1, stairs 4ft wide
151/19	Aug/12/2019	Aug/12/2019	Aug/20/2019	Tudor and Cashel	Wadsworth Lake	8	Major	Buildings; Fill/Grading	fill, dwelling, install septic, driveway, boardwalk and dock
153/19	Aug/15/2019	Aug/29/2019	Sep/6/2019	Faraday	wetlands	8	Minor	Buildings	building two 32'8"x10'4" roof extensions on either side of the existing dwelling
160/19	Aug/21/2019	Aug/29/2019	Sep/6/2019	North Kawartha	Chandos Lake	8	Minor	Buildings	building 2 additions plus an open deck to an existing dwelling being 64' to the shoreline
162/19	Aug/27/2019	Aug/29/2019	Sep/6/2019	North Kawartha	Chandos Lake	8	Minor	Buildings; Shoreline	replacing existing decks, stairs & shed along 12m of shoreline and shoreline repair
165/19	Aug/30/2019	Aug/30/2019	Sep/4/2019	HBM	Cordova Lake	5	Minor	Fill/Grading	installing a new septic system being 99.95' from the shoreline
169/19	Sep/4/2019	Sep/4/2019	Sep/6/2019	Marmora and Lake	Dickey Lake	2	Minor	Fill/Grading	replacing old septic system with a new septic system in exact same location being 61' to the shoreline