





November 21, 2019 CVCA Board Meeting Regulations Permit Reporting Reporting Period: September 11, 2019 to November 14, 2019				Reporting Period Summary					
				Permits Issued	46	Mean Turnaround	19.30		
				Calendar Days	64	Permit / Cal. Day	0.72		
				Working Days	45	Permit / Work day	1.02		
				Property Inquiries	19				
Permit no.	Application Submitted	Application Complete	Permit Issued	Township	Regulated Feature	Turnaround (Cal. Days)	Permit Complexity	Application Type	Project Details
005/19	Jan/30/2019	Oct/18/2019	Nov/13/2019	HBM	Round Lake	26	Minor	Shoreline / Watercourse	80' of shoreline stabilization with 2 rows of armourstone on a gabion stone base
027/19	Mar/14/2019	Sep/19/2019	Sep/23/2019	Highlands East	Paudash Lake	4	Major	Buildings	building a 8.6mx4m addition to the lake side of the existing dwelling being 18m from the shoreline
109/19	Jul/4/2019	Oct/21/2019	Nov/8/2019	Highlands East	Paudash Lake	18	Minor	Docks	repairing an existing 10'x32' crib dock
110/19	Jul/5/2019	Sep/5/2019	Sep/18/2019	HBM	Round Lake	13	Minor	Shoreline / Watercourse	removing 20m of gabion baskets at the shoreline and replaced with armourstone 2 tier high with armourston steps into the water
138/19	Jul/31/2019	Aug/22/2019	Oct/2/2019	HBM	Belmont Lake	41	Minor	Shoreline / Watercourse	16-19m of shoreline protection by replacing gabion cages with armourstion 2 tiers high
139/19	Jul/31/2019	Aug/2/2019	Sep/27/2019	Trent Hills	Rylstone Lake	56	Minor	Fill & Grading	excavation near the shorline to install a shore well being 3m from the shoreline
143/19	Aug/8/2019	Aug/12/2019	Sep/11/2019	Faraday	watercourse	30	Minor	Water Crossing (culvert or bridge)	replacing a failed culvert crossing
152/19	Aug/12/2019	Sep 6 2019	Sep/20/2019	Wollaston	Wollaston Lake	14	Minor	Shoreline / Watercourse	39m of shoreline protection using granite boulders
154/19	Aug/19/2019	Aug/29/2019	Oct/1/2019	Marmora and Lake	Twin Sister Lakes	33	Minor	Shoreline / Watercourse	proposed dredging to create 2 boant canals (4mx10m) to provide boat access to the front of the cottage
155/19	Aug/14/2019	Sep/9/2019	Sep/19/2019	North Kawartha	Chandos Lake	10	Minor	Buildings	to change the 10'x20' boathouse foundation and to replace existing deckin in front of boathouse

November 21, 2019 CVCA Board Meeting Regulations Permit Reporting Reporting Period: September 11, 2019 to November 14, 2019				Reporting Period Summary					
				Permits Issued	46	Mean Turnaround	19.30		
				Calendar Days	64	Permit / Cal. Day	0.72		
				Working Days	45	Permit / Work day	1.02		
				Property Inquiries	19				
Permit no.	Application Submitted	Application Complete	Permit Issued	Township	Regulated Feature	Turnaround (Cal. Days)	Permit Complexity	Application Type	Project Details
156/19	Aug/16/2019	Aug/28/2019	Sep/27/2019	North Kawartha	Chandos Lake	30	Minor	Fill & Grading	replacement of existing stone stairway from the cottage down to the dock
157/19	Aug/21/2019	Sep/5/2019	Oct/3/2019	Marmora and Lake	Twin Sister Lakes	28	Minor	Shoreline / Watercourse	45' of shoreline reconstruction with 1 row of 16+" armourstone on a gabion stone base
159/19	Aug/21/2019	Sep/6/2019	Sep/19/2019	Highlands East	Paudash Lake	13	Minor	Fill & Grading	replacement of septic system being 78' from the shoreline
161/19	Aug/26/2019	Aug/26/2019	Sep/18/2019	North Kawartha	Crowe River	23	Minor	Buildings	building a 12'x16' screened porch on rear of existing dwelling 145' to the shoreline
163/19	Aug/27/2019	Aug/29/2019	Sep/30/2019	North Kawartha	Chandos Lake	32	Major	Water Crossing (culvert or bridge)	to replace an existing culvert with 2 larger culverts and to install a small granular berms and build up the road to force spring run off to culvert location
164/19	Aug/23/2019	Sep/4/2019	Oct/3/2019	North Kawartha	Chandos Lake	29	Minor	Buildings	building a 653sqft garage, putting in a new full basement foundation being 17' from the shoreline and 15m of shoreline protection using the existing material
168/19	Sep/4/2019	Sep/18/2019	Sep/20/2019	North Kawartha	Chandos Lake	2	Minor	Shoreline / Watercourse	30 m of shoreline protection - replacing wood retaining wall with 72' of 3 tier high armourstone and steps into the water and 32' of boulders at a 3:1 slope
170/19	Sep/4/2019	Sep/23/2019	Sep/27/2019	Marmora and Lake	Crowe Lake	4	Minor	Buildings	raising the dwelling and reblocking the foundation and raising it an extra 1.5' being approximatley 33' to the shoreline

November 21, 2019 CVCA Board Meeting Regulations Permit Reporting Reporting Period: September 11, 2019 to November 14, 2019				Reporting Period Summary					
				Permits Issued	46	Mean Turnaround	19.30		
				Calendar Days	64	Permit / Cal. Day	0.72		
				Working Days	45	Permit / Work day	1.02		
				Property Inquiries	19				
Permit no.	Application Submitted	Application Complete	Permit Issued	Township	Regulated Feature	Turnaround (Cal. Days)	Permit Complexity	Application Type	Project Details
171/19	Sep/5/2019	Oct/21/2019	Oct/24/2019	HBM	Methuen Lake	3	Minor	Buildings	NC - replacing existing 26sqft rotting porch with a new 77sqft larger entry porch in same location being 37.1' from the shoreline (non-compliance; already completed)
172/19	Sep/5/2019	Oct/28/2019	Nov/5/2019	Highlands East	Paudash Lake	8	Minor	Shoreline / Watercourse	140' of shoreline protection using armourstone 3 tiers high
174/19	Sep/5/2019	Sep/6/2019	Oct/3/2019	North Kawartha	Chandos Lake	27	Minor	Buildings	demolishing existing dwelling and building a new 1426.5sqft dwelling being 43' from the shoreline and installing a new septic outside the regulated zone
175/19	Sep/6/2019	Sep/12/2019	Oct/25/2019	HBM	wetlands	43	Minor	Fill & Grading	depositing 8" "A" granular fill under 16"x16"x4" precast concret pad which as 8"x8"x16" perforated concrete block on top of it to support a 16'x70' mobile home and a 32'x10' attached deck
176/19	Sep/9/2019	Sep/24/2019	Sep/26/2019	North Kawartha	Chandos Lake	2	Minor	Shoreline / Watercourse	building a set of stairs to the existing front deck being 65.5' from the shoreline; 35m of shoreline protection with a wall of boulders. The back deck and stairs are outside the CVCA regulated zone
177/19	Sep/9/19	Sep/9/2019	Oct/9/2019	North Kawartha	Belmont Lake	30	Minor	Buildings	replacing an existing 348sqft "L" shped deck being 29'11" from the shoreline

November 21, 2019 CVCA Board Meeting Regulations Permit Reporting Reporting Period: September 11, 2019 to November 14, 2019				Reporting Period Summary					
				Permits Issued	46	Mean Turnaround	19.30		
				Calendar Days	64	Permit / Cal. Day	0.72		
				Working Days	45	Permit / Work day	1.02		
				Property Inquiries	19				
Permit no.	Application Submitted	Application Complete	Permit Issued	Township	Regulated Feature	Turnaround (Cal. Days)	Permit Complexity	Application Type	Project Details
179/19	Sep/9/2019	Sep/9/2019	Oct/11/2019	Wollaston	pond and wetlands	32	Minor	Buildings	building a new 26'x36' garage on a floating pad 10' higher than the pond 105' diagonally from the pond and building 6'wx24' veranda on both the east side and the west side of the existing dwelling on sono tubes 4' below grade and 7' above grade being 68' from the pond
180/19	Sep/9/2019	Sep/9/2019	Oct/7/2019	Tudor and Cashel	Mephisto Lake	28	Minor	Buildings	building a new 1260sqft dwelling with a walkout basement 18.9m from the shoreline, installtion of a new septic system, building a new 8.53mx12.19m garage being approximatley 43.5m from the shoreline, building a new deck 1m from the shoreline, building a retaining wall using material from the foundation preperation approximately 1m tall and proposed stairs from retaining wall to the new deck at the shoreline
181/19	Sep/10/2019	Sep/10/2019	Oct/7/2019	HBM	Belmont Lake	27	Minor	Shoreline / Watercourse	improve water flow in ditch by placing rip rap stone and filter clot along the ditch side for slope protection
182/19	Sep/10/2019	Sep/10/2019	Oct/10/2019	Marmora and Lake	Dickey Lake	30	Minor	Buildings	jack up the cottage and put in a full new ICF basement being 98' from the shoreline
183/19	Sep/12/2019	Sep/13/2019	Sep/20/2019	North Kawartha	Chandos Lake	7	Minor	Fill & Grading	installing a new septic system 125' from Chandos Lake & 65'-70' from an unnamed creek; the proposed bunkie is outside the CVCA regulated zone

November 21, 2019 CVCA Board Meeting Regulations Permit Reporting Reporting Period: September 11, 2019 to November 14, 2019				Reporting Period Summary					
				Permits Issued	46	Mean Turnaround	19.30		
				Calendar Days	64	Permit / Cal. Day	0.72		
				Working Days	45	Permit / Work day	1.02		
				Property Inquiries	19				
Permit no.	Application Submitted	Application Complete	Permit Issued	Township	Regulated Feature	Turnaround (Cal. Days)	Permit Complexity	Application Type	Project Details
185/19	Sep/16/2019	Sep/16/2019	Oct/4/2019	North Kawartha	Chandos Lake	18	Minor	Shoreline / Watercourse	90' of shoreline restoration using river stone at a 2:1 slope and 10-12 armourstone stairs up from the embankment
186/19	Sep/16/2019	Sep/27/2019	Oct/10/2019	HBM	Belmont Lake	13	Minor	Shoreline / Watercourse	100' of shoreline restoration using river rock at a 3:1 slope with 1 row of armourstone on top
187/19	Sep/16/2019	Sep/23/2019	Oct/10/2019	HBM	Belmont Lake	17	Minor	Shoreline / Watercourse	100' of shoreline restoration using river rock at a 3:1 slope with 1 row of armourstone on top
188/19	Sep/16/2019	Sep/16/2019	Sep/23/2019	HBM	PSW & unnamed watercourse	7	Minor	Buildings	building a 32'x48' pole barn being approximatley 53' to the 100' psw buffer zone
190/19	Sep/20/2019	Sep/23/2019	Oct/10/2019	HBM	Kasshabog Lake	17	Minor	Buildings	building a 560sqft addition to the east elevation of the existing cottage being 28' from the shoreline
191/19	Sep/20/2019	Sep/20/2019	Oct/17/2019	Marmora and Lake	Crowe Lake	27	Minor	Shoreline / Watercourse	70' of shoreline protection using rip rap rock at a 3:1 slop and rock steps to access the water and grade driveway and add minor fill screening
192/19	Sep/23/2019	Sep/24/2019	Oct/17/2019	North Kawartha	Chandos Lake	23	Minor	Shoreline / Watercourse	70' of shoreline protection using rip rap rock at a 3:1 slope
194/19	Sep/25/2019	Oct/4/2019	Oct/15/2019	HBM	Round Lake	11	Minor	Shoreline / Watercourse	60' of shoreline reconstruction with a gabion stone base and 1 row of armour stone & 3-4 limestone steps
196/19	Oct/1/2019	Oct/4/2019	Oct/10/2019	HBM	Kasshabog Lake	6	Minor	Buildings	replace the existing 9'6" x 30' deck with a new deck in the same foot pring 60' from the shoreline; they will sit on the existing 5 concrete pillars about 2' high

November 21, 2019 CVCA Board Meeting Regulations Permit Reporting Reporting Period: September 11, 2019 to November 14, 2019				Reporting Period Summary					
				Permits Issued	46	Mean Turnaround	19.30		
				Calendar Days	64	Permit / Cal. Day	0.72		
				Working Days	45	Permit / Work day	1.02		
				Property Inquiries	19				
Permit no.	Application Submitted	Application Complete	Permit Issued	Township	Regulated Feature	Turnaround (Cal. Days)	Permit Complexity	Application Type	Project Details
197/19	Sep/25/2019	Oct/4/2019	Oct/4/2019	North Kawartha	Chandos Lake	0	Minor	Fill & Grading	fill in about 15' of an old trench 30'x8'x2' and create a level area for a fire pit approximately 20' in diameter
199/19	Oct/3/2019	Oct/3/2019	Oct/25/2019	Marmora and Lake	East Twin Sisters Lake	22	Minor	Buildings	demolish existing cottage and building a new 35'x35' cottage on the same location being 20' from the shoreline with a cement block crawl space foundation
200/19	Oct/10/2019	Oct/10/2019	Oct/11/2019	HBM	Belmont Lake	1	Minor	Buildings	rebuilding of a new 36'x8'deck on piers being 25' from the shoreline
024/18	Mar/08/2018	Sep/26/2019	Oct/17/2019	North Kawartha	Chandos Lake	21	Minor	Buildings	proposed 30'x24' addition to the side of the existing dwelling and the proposed 12'x28'x16' "L" shaped deck extension being 137.5' from the shoreline
205/19	Oct/16/2019	Oct/17/2019	Nov/6/2019	Highlands East	Paudash Lake	20	Minor	Fill & Grading	septic replacement in the same location 15' from the house and 20m from the shoreline
206/19	Oct/16/2019	Oct/18/2019	Nov/6/2019	Highlands East	Paudash Lake	19	Minor	Fill & Grading	install a new septic tank and septic bed replacement being 70' from the shoreline
210/19	Oct/22/2019	Oct/22/2019	Nov/5/2019	HBM	Belmont Lake	14	Minor	Fill & Grading	installing a new septic system 56'5" from the shoreline
211/19	Oct/22/2019	Oct/22/2019	Oct/31/2019	HBM	Crowe River	9	Minor	Buildings	adding on an additional 60sqft to the north west side of the existing deck being 61'7" from the shoreline