

Regulations Report - September 12th, 2018 to November 7th, 2018

Permit No.	Date In	Date Out	Turn-around	Proposed Works	Permit Category	Waterbody	Municipality
COMPLETED PERMITS							
2 24 17	31-Oct-18	2-Nov-18	2	Teardown and Rebuild New Dwelling	Buildings	Chandos Lake	North Kawartha
0 94 18	6-Sep-18	18-Sep-18	12	Amended Permit - Building Addition	Buildings	Round Lake	HBM
0 96 18	11-Sep-18	21-Sep-18	10	Boathouse	Buildings	Paudash Lake	Highlands East
0 98 18	5-Oct-18	5-Nov-18	31	Teardown and Build New Dwelling	Buildings	Oak Lake	HBM
0 99 18	6-Sep-18	25-Sep-18	19	Teardown and Build New Dwelling	Buildings	Chandos Lake	North Kawartha
1 39 18	11-Sep-18	27-Sep-18	16	Shoreline Works; Fill; Boat Launch	Shoreline, Fill	Glanmire Lake	Tudor & Cashel
1 48 18	1-Nov-18	5-Nov-18	4	Amended Permit - Include septic	Fill	Chandos Lake	North Kawartha
1 54 18	27-Aug-18	13-Sep-18	17	Shoreline Erosion Control Works	Shoreline	Paudash Lake	Highlands East
1 55 18	25-Sep-18	2-Oct-18	7	Erosion Control Structure, Fill and Grading	Shoreline, Fill	Chandos Lake	North Kawartha
1 56 18	29-Aug-18	12-Sep-18	14	New Dock Anchored to Shoreline	Docks	Crowe River	Marmora & Lake
1 57 18	11-Sep-18	20-Sep-18	9	Boat Launch Reconstruction	Shoreline	Crowe Lake	Marmora & Lake
1 58 18	10-Sep-18	27-Sep-18	17	Shoreline Works - steps and landing	Shoreline, Fill	Belmont Lake	HBM
1 59 18	4-Sep-18	21-Sep-18	17	Drainage Trench, Driveway, Garage	Buildings, Fill	Wetlands	Wollaston
1 60 18	5-Sep-18	24-Sep-18	19	Repair to existing rock shoreline	Shoreline	Crowe Lake	Marmora & Lake
1 61 18	5-Sep-18	24-Sep-18	19	Repair to existing rock shoreline	Shoreline	Crowe Lake	Marmora & Lake
1 62 18	5-Sep-18	24-Sep-18	19	Replace retaining wall with rip-rap	Shoreline, Fill	Crowe River	Marmora & Lake
1 63 18	5-Sep-18	24-Sep-18	19	Replace retaining wall with rip-rap	Shoreline, Fill	Crowe River	Marmora & Lake
1 64 18	5-Sep-18	25-Sep-18	20	New Dwelling and Septic Installation	Building, Fill	Twin Sisters Lake	Marmora & Lake
1 66 18	3-Oct-18	4-Oct-18	1	Shoreline Erosion Control Works	Shoreline	Crowe Lake	Marmora & Lake
1 67 18	11-Sep-18	25-Sep-18	14	Boat Launch Reconstruction	Shoreline, Fill	Crowe Lake	Marmora & Lake
1 68 18	13-Sep-18	5-Oct-18	22	Boat Launch Reconstruction	Shoreline, Fill	Crowe Lake	Marmora & Lake
1 69 18	11-Sep-18	25-Sep-18	14	Addition and new garage	Buildings	Chandos Lake	North Kawartha
1 70 18	12-Sep-18	17-Sep-18	5	New Dwelling, Garage and Septic Installation	Buildings, Fill	Wetlands	HBM
1 71 18	14-Sep-18	5-Oct-18	21	Shoreline Erosion Control Works	Shoreline	Chandos Lake	North Kawartha
1 72 18	13-Sep-18	28-Sep-18	15	Teardown and Build New Dwelling	Buildings	Belmont Lake	HBM
1 74 18	25-Sep-18	2-Nov-18	38	Teardown and Build New Dwelling, Deck	Buildings	Kasshabog Lake	HBM
1 75 18	20-Sep-18	30-Oct-18	40	Replace retaining wall with rip-rap	Shoreline	Crowe River	Marmora & Lake
1 76 18	20-Sep-18	30-Oct-18	40	Replace retaining wall with rip-rap	Shoreline	Crowe River	Marmora & Lake
1 78 18	25-Sep-18	18-Oct-18	23	New Deck	Buildings	Paudash Lake	Highlands East
1 79 18	12-Oct-18	5-Nov-18	24	Replace wood retaining wall with armourstone	Shoreline	Belmont Lake	HBM
1 80 18	25-Sep-18	5-Oct-18	10	Walkout Basement and New Addition	Buildings	Sandy Lake	Highlands East
1 82 18	26-Sep-18	1-Oct-18	5	Septic System Installation	Fill	Coe Island Lake	Faraday
1 84 18	2-Oct-18	5-Oct-18	3	Fill Placement for Parking Area and Access	Fill	Wetlands	Wollaston
1 85 18	2-Oct-18	19-Oct-18	17	Shoreline Erosion Control Works - boulders and steps	Shoreline	Round Lake	HBM
1 87 18	3-Oct-18	19-Oct-18	16	Replace Failed Septic System	Fill	Chandos Lake	North Kawartha
1 88 18	5-Oct-18	2-Nov-18	28	New Deck, Garage and Septic Replacement	Buildings, Fill	Kasshabog Lake	HBM
1 90 18	16-Oct-18	5-Nov-18	20	Installation of 2 Culverts	Water Crossing	Wetlands and Watercourse	HBM
1 92 18	15-Oct-18	26-Oct-18	11	New Dwelling and Septic Installation	Buildings, Fill	Wetlands	Marmora & Lake
1 93 18	16-Oct-18	5-Nov-18	20	New Storage Shed	Buildings	Oak Lake	HBM
Permit Statistics			Property Inquiries		Non Compliance		
Permits Issued		39	Total: 20		Violations		
Calendar Days		56			Resolved	2	
Working Days		39			Received	3	
Mean Turn-Around Time					Total Open	22	
Calendar Days		16.87					
Permits per Day							
Permits / Calendar Day		0.70					
Permits / Working Days		1.00					