February 25,	2021					Reporting Period Su	nmary				
CVCA Board Meeting				Permits Issued	31 Mean Turnaround						
Regulations Permit Reporting				Calendar Days	36	Permit / Cal. Day			Crowe Valley		
Reporting Period: January 13, 2021 to February 18, 2021				Working Days	26 Permit / Work day			0.86 1.19	- Conservation		
				Property inquiries	-	21	Property inquiries complete	-	-		
	Application	1051001 y 10, 20			Turnaround						
Permit no.	Complete	Permit Issued	Township	<b>Regulated Feature</b>	(Cal. Days)	Application Type	Project Details				
028/20	Nov/5/2020	Feb/5/2021		Crowe Lake	92	Buildings	being 100' from the shoreline	0	a full basement and a new septic system		
007/20	1 (21 /2021	1 (24 /2024	Stirling-	Carrier Discon		Desiletin en		fro the sh	oreline and create a level 12'x12' seating		
097/20	Jan/21/2021	Jan/21/2021		Crowe River	ι ι	Buildings	area at the shoreline				
110/20	Nov/20/2020	lan /27 /2021	North	Chandes Lake		Duildingo		emo/repla	ce unsafe cribbing/walkway; replace dock		
116/20	Nov/30/2020	Jan/27/2021	Kawartha	Chandos Lake	58	Buildings	& ramp.				
119/20	Jul/27/2020	Jan/20/2021	Wollaston	Vader Lake	177	Buildings	Construct 22'x38' cottage; requires 15-3'x3'x4' excavations for footings, septic tank to be placed west of the prosed dwelling (minimum 100' from stream and shoreline)				
127/20	Aug/6/2020	Jan/21/2021	Trent Hills	Crowe River and wetlands	168	Buildings	build a new 26'x41' 2 storey dwelling with a full walk out basement approx 50' from the shoreline, installing a new septic and building a new 24'x26' garage approx 70' from the shoreline				
127720	////2020	5411/21/2021	Trene This	wetlands and	100	buildings					
128/20	Aug/17/2020	Jan/22/2021	Limerick	watercourse	159	Buildings	building a 28'x48' hunting camp on concrete piers being 240m from the road				
128/20	Aug/17/2020	Juli 22/2021	Limenck	Limerick Lake and St.		Duluings					
130/20	Aug/11/2020	Jan/27/2021	Limerick	Ola Lake		Shoreline/watercourse	clean up the shoreline of the old meta	d rail way ties			
	Aug/11/2020	Juli 27/2021	Highlands		10.5	Shoreline, watercourse	adding a 480sqft 2 storey addition wit	t halcony on the 2nd storey being 26'			
131/20	Aug/17/2020	Jan/22/2021	U	Paudash Lake	158	Buildings	from the shoreline	10 120591	success on the 2nd storey being 20		
131/20	////2020	5411, 22, 2021	North	Faudasii Lake	150	Dunuings		addition	and to install a new septic system being		
133/20	Oct/21/2020	Feb/1/2021		Chandos Lake	103	Buildings	2.5m from the existing deck to the sho		and to instand new septie system being		
	000/21/2020	100/1/2021	North	chandos Eake	103	buildings			Iders at a 2:1 slope to cover up existing		
144/20	Aug/12/2020	Jan/29/2021		Chandos Lake	170	Shoreline/watercourse	broken concrete and rebar				
	/ (06/ 12/ 2020	5411/25/2021	Marmora	chanaos zanc							
145/20	Aug/13/2020	Feb/3/2021		Beaver Creek	174	Buildings	rebuild a ne 35'x11'6" deck with an aw	ning bein	g 57' to the shoreline		
110/20	////20/2020	100/0/2021		Beaver creek	1 1/1	Dunumps	building a wooden crib for an existing dock under the pole section of the ramp and the				
147/20	Sep/9/2020	Feb/1/2021	НВМ	Belmont Lake	145	Docks	land end of the bridge				
			North				rebuild the existing 13'x34'5" 2 storey	boathous	e with upper and lower decks being right		
148/20	Oct/15/2020	Feb/3/2021	Kawartha	Chandos Lake	111	Buildings	at the shoreline				
			North	1	1		12m of shoreline protection using gra	nite rip ra	p placed on a 3:1 slope on a woven		
152/20	Aug 31 2020	Jan/27/2021	Kawartha	Chandos Lake	149	Shoreline/watercourse	geotextile cloth				
	-		Marmora		1						
153/20	Oct/23/2020	Jan/28/2021	and Lake	Beaver Creek	97	Buildings	building a 20'x36' garage 82.5' from th	e shorelin	le		
			Tudor and						ng lakeside deck an extra 12' being 100'		
157/20	Sep/11/2020	Feb/3/2021	Cashel	Mann Lake	145	Buildings	•		I install a new septic system being 110'		
169/20	Sep/9/2020	Feb/2/2021	Marmora and Lake	Dickey Lake	146	Water Crossings(Culverts/Bridges)	replace a failed culvert with a new 10	50mm x 1	7m CSP culvert		
173/20	Sep/14/2020	Feb/3/2021	Kawartha	Chandos Lake	147	Shoreline/watercourse	10m of shoreline protection using exis	ting rocks			
				Entering of Lance		·	2011 of shoreline protection using exis	Jung rocks	-		
179/20	Sep/21/2020	Feb/16/2021	HBM	Belmont Lake	148	Shoreline/watercourse	30' of shoreline protection by installin	g random	stone boulders on a 2:1 slope		
180/20	Oct/29/2020	Feb/5/2021	НВМ	Belmont Lake	99	Shoreline/watercourse	46' fo shoreline protection using 2 rov steps	vs of armo	ourstone on a gabion base and limestone		

February 25, 2021				Reporting Period Summary						
CVCA Board Meeting				Permits Issued	31	Mean Turnaround 114			A 1	
Regulations Permit Reporting				Calendar Days	36	Permit / Cal. Day 0.8			Crowe Valley	
Reporting Period: January 13, 2021				Working Days	26	Permit / Work day 1.19			Conservation	
to February 18, 2021			Property inquiries received:		21 Property inquiries comp		iete: 22			
Permit no.	Application Complete	Permit Issued	Township	Regulated Feature	Turnaround (Cal. Days)	Application Type	Project Details			
185/20	Sep/30/2020	Feb/16/2021	нвм	Round Lake	139	Shoreline/watercourse	retaining wall at the boat launch with	4'W limest 1 rowe of	a random stone boulders to existing one steps - replacement of a 12' concrete 16" armoustone and remove existing stone slabs to existing slope and grade	
			North					an boulder	s over non-woven geotextile cloth at a	
186/20	Sep/22/2020	Feb/12/2021		Chandos Lake	143	Shoreline/watercourse	3:1 slope			
202/20	Jan/6/2021	Feb/5/2021	Highlands East	Paudash Lake	30	Fill&Grading (Floodplain)	installation of a septic system being a	pprox 39.8	6m from the shoreline	
203/20	Oct/16/2020	Feb/21/2021	нвм	Wetland	128	Buildings	building a new 52'x48' dwelling incluc from the wetalnds and install a new o	0 1	t and install new septic system being 180'	
212/20	Oct/29/2020			PSW		Buildings	to rebuild a 26'x26' burnt garage with a loft being 35.87' from Baker Rd and 15'61/2" from the existing dwelling			
213/20	Nov/30/2020	Feb/5/2021		Crowe Lake and Creek	67	Buildings	building a 30'x15' rain shelter with no wall or floor being 140' from the shoreline and 60' from the creek			
216/20	Nov/4/2020	Jan/20/2021	НВМ	Round Lake	77	Docks	convert existing dock to a lift dock by bolting existing landing to stone steps and install a new 10'x6'w ramp to have the tower folded into the frame			
218/20	Dec/17/2020	Feb/5/2021	НВМ	West Twin Lake	50	Shoreline/watercourse	130' of shoreline protection using 2 rows of armour stone on a gabion stone base and toe of slope			
221/20	Nov/26/2020	Feb/21/2021	Ŭ	Paudash Lake and wetlands	87	Buildings	building a 24'x30' garage being appro from watercourse and shoreline	ximatley 16	58' from the wetland buffer zone, 253'	
001/21	Jan/6/2021	Jan/12/2021	North Kawart	Chandos Lake	6	Fill&Grading	replace existing septic thank and filte	r bed 85 <mark>'</mark> fr	om the shoreline	
019/21	Feb/9/2021	Feb/12/2021	North Kawart	Chandos Lake	3	Buildings	demolish existing garage and build a coolection point and approx 205' fror			







