February 24, 2022				Reporting Period Summary					
CVCA Board Meeting				Permits Issued	7	Mean Turnaround 33		33.43	Crowe Valley
Regulations Permit Reporting				Calendar Days	35	Permit / Cal. Day 0.		0.20	
Reporting Period:		January 7, 2022		Working Days	24	Permit / Work day		0.29	conservation
	to	to February 11, 2022		Property inquiries received:		25	Property inquiries complete: 9		
	Application			Regulated	Turnaround				
Permit no.	Complete	Permit Issued	Township	Feature	(Cal. Days)	Application Type	Project Details		
157/21	Dec/29/2021	Jan/11/2022	North Kawartha	Chandos Lake	13	Buildings (All Other-Natural hazard+Setback)	building 2 replacement 32'x30' 2 storey dwelling w spetic systmes bheind the proposed dwellings	rith a full wal	k out basement both being approx. 46.9m from the shoreline and installing 2
214/21	Dec/15/2021	Feb/4/2022	нвм	Belmont Lake	51	Shoreline/watercourse	30' of shoreline protection by using 16" armourstor steps replacing wooden ones.	ne, building	a 30'x10' flagstone patio behind armourstone wall and a set of 7 limestone
298/21	Oct/25/2021	Jan/26/2022	North Kawartha	Chandos Lake	93	Buildings (All Other-Natural hazard+Setback)	already built a 10'x30' deck to the side of the existi	ing dwelling	being 54' from the shoreline
324/21	Dec/15/2021	Jan/13/2022	Highlands East	Paudash Lake	29		building a 42'x60' dwelling being 90' from the shore 24'x31' garage behind the proposed septic and 40'		tall a new septic system behind the proposed dwelling and building a new d.
327/21	Jan/18/2022	Jan/26/2022	Faraday	Coe Island Lake	8	Buildings (All Other-Natural hazard+Setback)	building a 28'x38' - 3 bay garage with a loft being s	etback 180' f	rom the shoreline
329/21	Jan/4/2022	Jan/14/2022	Highlands East	Paudash Lake	10	Docks	replacement of an existing 8'x16' permanent crib d	lock piling an	d platforms
005/22	12-Jan-22	Feb/11/2022	нвм	Round Lake	30	Fill&Grading (All Other-Natural haza	installation of a new septic system to replace the o	old one being	5' behind the existing dwelling







